COMPLETION REPORT

1	Name of the work	Reserve fund for emergency Maintanance of UGD at Sidedahalli Village Limit in Bagalagunte Ward No MHR Layout, Sayhadri Layout & Kirloskar Layout.
2	Sanctioned Estimate No. & Date	T.No: BBMP/244/14-15 dt:-3.2015
3	Head of Account which is chargeable	Plan 1771
4	Instrument Order NO. & Date	WO No: BBMP/DY/15-16 dt:-15.4.2015
5	Name Of Contractor	Technical Manager (west) Karnataka Rural Infrastructure Development Limited, Project Implementation unit, Madhavanagara Bangalore 560 001..
6 a	Time Stipulated for Completion of work	90 days
b	Delay in Exculpation of Work	
7	Measurement recorded in	MB No 3413/14-15 page No 341210-219/a
8	Check Measurement of the Asst	BB No 3413/14-15 page No 341210-219/a
9	Name of the office/official in charge of the work	AEE (OSD)
10	a) Asst. Eng/junior Eng	D.S. ಮಂಜುನಾಥ
	b) Asst. Exe Engineer	ರಂಗನಾಥ

Sanctioned Estimate Amout	Amout Claims As per Actually Vide As per bills	Excess	Savings
3-ಲಕ್ಷ	292094ರೂ	—	7906ರೂ

1) Certified that the above work has been completed within the stipulated time noted in the
2) Certified that the contractor has delayed and completed the work for which necessary fine recovered
3) Certified that the above work has been executed by the contractor satisfactory in

ASSISTANT ENGINEER.

ASSIATANT EXECUTIVE ENGINEER

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಇಂಜಿನಿಯರರು
ಜ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬಾಗಲಗುಂಟೆ, ಬೆಂಗಳೂರು - 560 073

EXECUTIVE ENGINEER
Bruhat Bangalore Mahanagara Palike,
Dasarahalli Zone, Bangalore-57.

ಮುಖ್ಯ ಅಭಿಯಂತರರು